

Ds463P Service Manual

| Tandem Drive Axle - Single Reduction Carriers | | | |
|--|------------------|-------------|-----------------|
| DS461P - Standard Carrier | | | |
| 18.00° Spiral Bevel Gearing Side Gear # 83401 | | | |
| These new carrier units will directly replace models DS461P, DS462P, DS463P, DS521P and DS581P with no modifications. | | | |
| Ratio | Side Gear Spline | New Carrier | Notes |
| 3.55 | 36 Inv | 673242 | |
| 3.70 | 36 Inv | 674514 | |
| 3.90 | 36 Inv | 674811 | |
| 4.11 | 36 Inv | 674315 | |
| 4.33 | 36 Inv | 674516 | |
| 4.56 | 36 Inv | 674317 | |
| 4.88 | 36 Inv | 674318 | |
| 5.29 | 36 Inv | 674813 | |
| 5.43 | 36 Inv | 674519 | |
| 6.17 | 36 Inv | 674707 | |
| DS461 - Standard Carrier and No Spin Carrier | | | |
| 18.00° Spiral Bevel Gearing Side Gear # 83401 No Spin # 130031 | | | |
| These new carrier units will directly replace models RS461, RS462, RS463, RS521, RS581, RS461NS, RS462NS, RS463NS, RS521NS and RS581NS with no modifications. | | | |
| Ratio | Side Gear Spline | New Carrier | With No Spin |
| 3.55 | 36 Inv | 673243 | |
| 3.70 | 36 Inv | 674520 | 122976 |
| 3.90 | 36 Inv | 674812 | |
| 4.11 | 36 Inv | 674321 | 123001 |
| 4.33 | 36 Inv | 674522 | 122414 |
| 4.56 | 36 Inv | 674323 | |
| 4.88 | 36 Inv | 674324 | 123002 |
| 5.29 | 36 Inv | 674814 | 509031 |
| 5.43 | 36 Inv | 674525 | 217108 |
| 6.17 | 36 Inv | 674709 | 123003 |
| 6.50 | 36 Inv | 674710 | |
| 6.82 | 36 Inv | 673250 | |
| 7.17 | 36 Inv | 678115 | |
| DD461P - Diff Lock Carrier | | | |
| 18.00° Spiral Bevel Gearing Side Gear # 83401 | | | |
| See Note 1. These new carrier units will directly replace differential lock models DD461P, DD462P, DD463P, DD521P, DD581P and models DD540P with no modifications. | | | |
| Ratio | Side Gear Spline | New Carrier | Notes |
| 3.55 | 36 Inv | 673226 | |
| 3.70 | 36 Inv | 673227 | |
| 3.90 | 36 Inv | 673318 | |
| 4.11 | 36 Inv | 673229 | |
| 4.33 | 36 Inv | 673230 | |
| 4.56 | 36 Inv | 673331 | |
| 4.88 | 36 Inv | 673232 | |
| 5.29 | 36 Inv | 673333 | |
| 5.43 | 36 Inv | 673334 | |
| 6.17 | 36 Inv | 673235 | |
| Note 1: The DD540P and RS540 Carriers were discontinued in 2010. They are replaced by the DD461P and RS461 service carriers. The Non-Pump DD540 models are N/A, you must purchase a DD461P (with pump) for service. | | | |
| RD461 - Diff Lock Carrier | | | |
| 18.00° Spiral Bevel Gearing Side Gear # 83401 | | | |
| These new carrier units will directly replace models RD461, RD462, RD463, RD521, RD581 and models RD540 with no modifications. | | | |
| Ratio | Side Gear Spline | New Carrier | Notes |
| 3.55 | 36 Inv | 673236 | |
| 3.70 | 36 Inv | 673237 | |
| 3.90 | 36 Inv | 673338 | |
| 4.11 | 36 Inv | 673239 | |
| 4.33 | 36 Inv | 673240 | Replaces 673241 |
| 4.56 | 36 Inv | 673341 | Replaces 673242 |
| 4.88 | 36 Inv | 673342 | |
| 5.29 | 36 Inv | 673343 | |
| 5.43 | 36 Inv | 673344 | |
| 6.17 | 36 Inv | 673247 | |
| 6.50 | 36 Inv | 673348 | |
| 6.82 | 36 Inv | 673349 | |
| 7.17 | 36 Inv | 673681 | |

42

File Name: Ds463P Service Manual.pdf
Size: 3508 KB
Type: PDF, ePub, eBook
Category: Book
Uploaded: 21 May 2019, 22:23 PM
Rating: 4.6/5 from 607 votes.

Status: AVAILABLE

Last checked: 19 Minutes ago!

In order to read or download Ds463P Service Manual ebook, you need to create a FREE account.

[Download Now!](#)

eBook includes PDF, ePub and Kindle version

- [Register a free 1 month Trial Account.](#)
- [Download as many books as you like \(Personal use\)](#)
- [Cancel the membership at any time if not satisfied.](#)
- [Join Over 80000 Happy Readers](#)

Book Descriptions:

We have made it easy for you to find a PDF Ebooks without any digging. And by having access to our ebooks online or by storing it on your computer, you have convenient answers with Ds463P Service Manual . To get started finding Ds463P Service Manual , you are right to find our website which has a comprehensive collection of manuals listed.

Our library is the biggest of these that have literally hundreds of thousands of different products represented.



Book Descriptions:

Ds463P Service Manual

Rear Axle Pinion Assembly Parts Exploded View. Forward Axle Parts List. How To Use Illustrated Parts List. Sinotruk Howo Heavy Duty Truck Parts Heavy Truck Rear Axle DS404 Eaton Differential Parts Diagram 1951 Chevy Truck Front Axle Chevy Rear. Eaton Differential Parts Manual. Service Manual Eaton Fuller HeavyDuty Transmissions. Remove the axle. Eaton Corporation reserves the right to discontinue or modify its models. Eaton DS404 Front Carriers Differential Assemblies For Sale. DST40 DS404 Torsionally Tuned 58 DST40P DS404P 58 DST41 DS404. Ordering Parts Note Model ID tag may read DS404P or DS405P. Corporation, presents this Parts Book as an aid in the identification and procurement of replacement parts for. The information included covers the locate information in this book and to identify the correct parts for servicing. Use the Contents or page false Literature Illustrated Parts List Tandem Drive Axle Illustrated Parts List PDF, 2MB Sales Literature 404 Tandem Axle Family Product Card PDF, 1MB Illustrated Parts List. Kia Spectra5 Repair Manual more. The description and specifications contained in this service publication are current at the time of printing. Illustrated Parts List. DD405P Notes. 24 PINION BRG SPACER KIT. Page 3 Introduction Introduction A service carrier is a new differential carrier used to replace current models or upgrade older axle models to current model configurations. Yokes are not included unless otherwise noted. Use this book to determine which service carrier to order. Some applications require a new yoke and slinger, details are included with model descriptions. Unique part numbers have been established for each new service carrier. Please use the new service carrier part numbers when ordering. Below is a listing of our most commonly used kits. These new carrier units will directly replace model S14S110FR with no modifications. These new carrier units will directly replace model S16S130 with no modifications. <http://www.lad1908.org/userfiles/cs74q-color-quad-processor-manual.xml>

- **ds463p service manual, ds463p service manual, ds463p service manual, ds463p service manual pdf, ds463p service manual download, ds463p service manuals, ds463p service manual free, ds463p service manual.**

These new carrier units will directly replace model S16S132 with no modifications. These new service only carrier units will directly replace model 19050S with no modifications. Model on ID tag may be RL344. Model on ID tag may be RS344. These carriers are specifically designed for noise sensitive applications. Model on ID tag may be RS404. These units can be used as replacements for models 23070D when a new yoke and slinger is used. See yoke section for proper selection. For early made models 19420, 23420 and 26420 use these units these and a new yoke and slinger. Model on ID tag may be R46170 or R46170NS. These new carrier units will directly replace single axle models S23190E, S26190E and S30190E with no modifications. See Note 1 with regards to Flange Thickness. These new carrier units will directly replace tandem axle models RS404 and RS405 and single axle models 21060S and 22060S with no modifications. Note 1 Side Gear Ratio Spline NonPump Carrier Pump Carrier DDH40P Diff Lock High Performance Carrier 15. These new carrier units can be used as a replacement for models DS4616P and DS4636P with no modifications. Please note that the part numbers listed are PRODUCTION part numbers and are for reference only. The part number needed for service may vary. For additional informatin see Service Bulletin ABIB0607. In March 2006, Dana discontinued offering all "Reverse Air" D404 family carriers. Page 60 Hybrid Carriers Hybrid Carriers In September 2004, the following "HYBRID" carriers shown below were formally discontinued by Spicer due mostly to low sales volume. Hybrid carriers were designed to service older vehicles the used axles configured with early designed side gear spline

configurations. Replacement carriers for those vehicles are still available, but now the axle shafts MUST also be updated. Note in some cases yokes require pgrading and should be replaced if replacing older design axles. All rights reserved. Ready to

They run two shifts so we no very little down time. Been buying trucks from Sam for over twenty years and you will not meet a more honest and decent person.CENTRAL you rock! LAIN NorWayne 0034 01 Mar 18 Its a great to pickup a bus that was repaired. Herman DeBerry 0139 21 May 18 Was greeted by more than one person. Gave me access to the waiting room while I waited for a colleague. Don Bouchard 2143 08 Jan 18 I work for a business called Equipment Works Inc. We do a lot of business with Central Truck Center because of their exceptional and outstanding customer service. I tend to deal with David, Junior, or Crystal on the parts counter. These two gentlemen and gal really know there stuff. They have gone above and beyond. I also tend to deal with driver Eddy a lot very courteous and professional. I couldnt ask for better kind of people to order parts from on a daily basis. Keep up the good work guys and lady. You ROCK! John Gonzalez 1504 07 Aug 19 Roger in service is great. He always seems to find a way not only to charge you for a arm but also a leg. What an amazing know it all.Whom, constantly shows great pride and empathy for overcharging customers for simple service fixes or diagnosis.Who holds this title Did you buy the vehicle new. Has the vehicle ever been in any accidents. Cost of repairs Where Has the vehicle ever had paint work performed. Is the title designated Salvage or Reconstructed. Any other. Additional terms, conditions and fees may apply. Equal opportunity lender.We have all of your used truck needs; and we will find your truck if we do not have it.

<http://superbia.lgbt/flotaganis/1655942007>

trucks for sale with day cabs, which are well suited for local and regional usage, as well as models with sleeper cabs, which are ideal for long haul trucking across the country. You'll also find trucks for sale on TruckPaper.com from many other manufacturers, with popular models including the Peterbilt 386, Volvo VNL64T, Kenworth T660, International Prostar, and Mack Pinnacle. Many of these brands offer models with day cabs or sleeper cabs as well. Equal opportunity lender. Wed, July 31, 2019 1242 PM Wed, Aug 12, 2020 1245 PM ISX Cummins engine 475 hp. Engine conforms to the year 2000 US and California EPA Scale Weight 8288 kg Wed, May 6, 2020 1231 PM Wed, Aug 7, 2019 1222 PM Cummins ISL365, 273,198 ACTUAL MILES!, Eaton Fuller FRO12210C 10 spd, Air Ride Suspension, 12000 lb Front, DSP40 Rears, 182 in. Wheel Base, Alum Outers, Wet Kit, new turbo just installed Wed, April 1, 2020 1239 PM Fleet Reduction Auction Liquidating Trucks, Trailers and Other Equipment Call For Details 2007 KW T800 Pre Emission Unit Wet Kit 10 Speed CAT C15 475 HP Air Ride 3.55 Cruise Locking Diff 52K GVWR PL PM PW Htd Mirrors Call to Schedule a Demo or Inspection Wed, April 24, 2019 1249 PM Cummins ISM, 385 Horsepower, 341,898 Actual Miles, Wet Kit, Engine Brake, Three Pedal Autoshift, Diff Lock, Air Ride Suspension 12,000 lb. Front, 40,000 lb. Rears, 178 Wheel Base, Tilt, Cruise, Rust Free California Truck, Aluminum Wheels, Came From A Municipality.

Thu, Dec 26, 2019 157 PM Cummins ISM, 385 Horsepower, 255,871 Actual Miles, Two Line Wet Kit, Engine Brake, Three Pedal Autoshift, Diff Lock, Air Ride Suspension 12,000 lb. Front, 40,000 lb. Rears, 178 Wheel Base, Tilt, Cruise, Rust Free California Truck, Aluminum Wheels, Came From A Municipality. Wed, Jan 29, 2020 1134 AM Cummins ISM, 385 Horsepower, 303,290 Actual Miles, 2 Line Wet Kit, Engine Brake, Three Pedal Autoshift, Diff Lock, Air Ride Suspension 12,000 lb. Wed, May 27, 2020 1218 PM Cat C13, 430 Horsepower, 604,000 Actual Miles, Eaton Fuller 10 Speed, Air Ride Suspension, 178 Wheel Base, Diff Lock, New 11R25.5 Steers, New Rear Rubber, Dual Exhaust, Daylight Doors, Sliding 5th, Southern Truck, Tilt, Cruise, AC Thu, Dec 26, 2019 157 PM Cat C15 6NZ Engine brake. Front Axle 13,250 lb. Rear Axle 40,000 lb. New 11R. 24.5 steer tires. All wheels are Aluminum. Rear end r. Wed, March 11, 2020 1215 PM Wed, Nov 7, 2018 100 PM Wed, Nov 7, 2018 100 PM Buyers premium included in price 3% Thu, Dec 26, 2019 156 PM Wed, Nov 7, 2018 100 PM Wed, Dec 11, 2019 1226 PM Wed, Aug 14, 2019 1246 PM Wed, July 10, 2019 1243 PM Wed, Nov 14, 2018 1117 AM Wed, Nov 14, 2018 1117 AM Buyers premium included in price 3% Wed, Nov 13, 2019 1128 AM Cat 3176 diesel that starts right up and runs great. 350 hp 13 speed transmission with Jake brake. Clean 20' aluminum bed with cargo doors and brand new shurlok tarp. Bed been welded in a few places see pics. All service recor. Wed, Sep 25, 2019 1224 PM Wed, Oct 17, 2018 1140 AM WB, alum wheels, Edwards 100112 pump, NVE pump, NuFlo MCII Flow Analyzer Wed, Oct 24, 2018 1247 PM Tag axle 950,000 miles. Very good running engine, good clean truck. Tommy Lift. Detroit Engine, 10 Speed Transmission. Tag axle, Jake Brake. Heated van. Air Ride. Very. Wed, June 24, 2020 1020 AM Use the TAB key to move between fields. Currency Capital, LLC is an independent finance company and is not the manufacturer or supplier of any equipment. Equal opportunity lender.

Advance prebidding begins 7 days before the close of each online heavy equipment auction. Look for names like Peterbilt, Freightliner, Kenworth, International, Mack, Volvo, Ford, GMC, Sterling, Western Star, and many others. AuctionTime.com is owned and operated by the publishers of Truck Paper and TruckPaper.com. Discover everything Scribd has to offer, including books and audiobooks from major publishers. Start Free Trial Cancel anytime. Report this Document Download Now Save Save CV713 Granite Motor AMI300 ASET.pdf For Later 0 ratings 0% found this document useful 0 votes 44 views 4 pages CV713 Granite Motor AMI300 ASET.pdf Uploaded by Lenny Virgo Description Full description Save Save CV713 Granite Motor AMI300 ASET.pdf For Later 0% 0% found this document useful, Mark this document as useful 0% 0% found this document not useful, Mark this document as not useful Embed Share Print Download Now Jump to Page You are on page

1 of 4 Search inside document Browse Books Site Directory Site Language English Change Language English Change Language. Rebuilt in Last 6 months Cummins ISX Engine No Mechanical Issues Starts, Runs, Works. WB, PTO, RS Body 21 ft alum box. WB, PTO, Godwin 20 ft alum box, liner. WB, PTO, alum wheels, Godwin 21 ft alum box, liner. WB, PTO, alum wheels, 20 ft alum box, box vibrator. WB, alum wheels, 20 ft alum box, liner. WB, PTO, alum outers, 20 ft box. WB, alum outers, 19 ft box. LOCATED IN NASHVILLE TN South Vienna, OH, USA Auction 1994 KENWORTH T800 Manufacturer Kenworth Model T800 Caterpillar, Eaton Fuller 10 spd, spring over beam susp, 214 in. WB, alum frt, 16 ft box. WB, 20 ft alum box. Yes No Please tell us more so that we can improve our website How can we get in touch with you optional Send Feedback Thank you for making Machinio better. Your feedback is greatly appreciated. For a better experience, we recommend using another browser. Learn more Facebook Email or phone Password Forgotten account.

Sign Up See more of Camiones Seminuevos VRG on Facebook Log In or Create New Account See more of Camiones Seminuevos VRG on Facebook Log In Forgotten account. Transportation service Camiones y Maquinaria en Queretaro Motor vehicle company Recent post by Page Camiones Seminuevos VRG 18 September at 0918 ENTREGA DE AMBULANCIA RAM PROMASTER 2500 MODELO 2015. If you have any suggestions on how to improve our site, please let us know. Your suggestions and feedback immensely help us improve our site. Quickly jump to this search by going to My Account and Saved Searches. Privacy Policy. CAT Engine, Manual Transmission. 47,000 lb 21 319 kg maximum lifting capacity 101 30.78 m maximum sheave height 144 43.89 m maximum sheave height with 2644 7.9213.41 m jib 2992 8.8428.04 m foursection We are asset liquidators for 40 years, 20 years on eBay. Some dents on roof Body Fair to Average Bumpers Good. Operation normal Lights All lights operational INTERIOR Seats No rips or tears. Some wear on rubber pad DRIVE Engine Type Caterpillar CAT C15 435 HP 6 Cylinder Turbo Diesel Engine Condition Good cold start, good compression, cylinder balance normal, good power, minimal blowby Trans Type 13 Speed Manual Trans Condition Good. Operation normal Final Drives Good. Operation normal Power Steering Good. We drove it 400 miles with no issues. INSPECTOR Robert Sorrells 801 4736800 LOCATION Orem, UT 84057 NEAR Salt Lake City Area Check out all our inventory at www.GlobalRemarketing.net We have network of shipping brokers coast to coast allowing for the best shipping rates possible. We pride ourselves in getting quick quotes and for the lowest cost poss. Effective July 1, 2004, Dana Spicer eliminated the core charges for all axle carriers. Using this Book Existing Axle Model to Replacement Carrier Model All carriers are identified by axle model. Follow these steps to locate the appropriate service carrier for your existing axle model 1.

Find the axle model identification of your existing drive axle model as listed in the Axle Model Index. 2. Go to the page referenced and select the proper carrier. Note Be sure to pay close attention to the notes to prevent selecting the wrong part. Using this Book Yoke Selection This book contains a section of Yoke Selection Instructions see Table of Contents. This section is referred to throughout the book. This information will help to locate information in this book and to identify the correct parts for servicing. For the latest product additions and program details, visit us on the web at Spicer MODEL HEAD RATIO SPEC. CUST. PART NO. Single Drive Axle SERIAL NO. Spicer lube part numbers are shown below. Contact your nearest distributor. Proof of purchase along with new carrier serial number and vehicle information is required. Spicer FE 75W90 Fuel Efficient Synthetic Gear lubricant. Spicer Part Number Description Spicer Part Number Description Spicer Part Number Description FE75W90G 1 gallon jug 80W140G 1 gallon jug XFE75W90G 1 gallon jug FE75W90P 5 gallon pail 80W140P 5 gallon pail XFE75W90P 5 gallon pail FE75W90D 55 gallon drum 80W140D 55 gallon drum XFE75W90D 55 gallon drum Go to for full product specifications, OEM approvals, lubricant characteristics, copy of the MSDS sheet and to use our Fuel Savings Calculator to quantify the 1% fuel savings. Warranty Returns Service Carriers Dealers are to call Penske Logistics telephone Press Option 0, identify that the return is for Dana Drive Axle. Identify the

carrier before ordering the hardware kit. Note B For replacement options, please see IASS model information on page 64. Note C Replacement carriers are no longer offered by Dana. Note D 461 hybrid carriers are nla update to current 461 carriers and upgrade axle shafts. Note E 19050T MML designed with 30 involute spline side gears were discontinued.

These carriers are built to a unique design for Navistar applications beginning in October 2000 and have unique pinion seal127591 and pinion yokes. Model on ID tag may be RS344. Use axle housing hardware kit Note 1 In certain Navistar vehicle applications, original Dana production carriers are identified as 21060S, 21060L, 21060T and 21060D. These carriers are built with 39 Involute spline side gears. Carriers with 39 Involute spline side gears are sold as 19060S, 19060L, 19060T and 19060D. Be sure to check spline configuration before ordering replacement carriers S BC GenTech Quiet Gearing Spline 39 Involute Gearing Hypoid Side Gear Part Number Fastener Kit These new carrier units will directly replace single axle models 17060S BC and 19060S BC with no modifications. When choosing replacements of these carriers, be sure to consult the OEM or verify the actual part numbers from the serial tag before ordering carriers. For ratios or options not shown, call Dana for availability. New Carrier SBC430EX 19060SBC430CF SBC478EX 19060SBC478CF SBC488EX 19060SBC488CF SBC529EX 19060SBC529CF SBC557EX 19060SBC557CF SBC617EX 19060SBC617CF SBC650EX 19060SBC650CF SBC717EX 19060SBC717CF Note The service carriers listed above have a thin flange design. Use axle housing hardware kit Note 1 In certain Navistar vehicle applications, original Dana Production Carriers are identified as 21060S, 21060L, 21060T and 21060D. Carriers with 39 Involute spline side gears are sold as 19060S, 19060BC, 19060L, 19060T and 19060D. Note 1 In certain Navistar vehicle applications, original Dana production carriers are identified as 21060S, 21060L, 21060T and 21060D. New Carrier SRBC430EX 19060SRBC430CF SRBC478EX 19060SRBC478CF SRBC529EX 19060SRBC529CF SRBC557EX 19060SRBC557CF SRBC617EX 19060SRBC617CF SRBC650EX 19060SRBC650CF SRBC717EX 19060SRBC717CF Note The service carriers listed above have a thin flange design. Be sure to check spline configuration before ordering replacement carriers.

28 31 New Service Carriers Single Drive Axles Single Axle Single Reduction Carriers 19060D Diff Lock Carriers Spline 39 Involute Gearing Hypoid Side Gear Part Number Fastener Kit These new carrier units will directly replace single axle models 17060D, 17060D PB, 19060D and 19060D PB and tandem axle model RD344 with no modifications. Model on ID tag may be RD344. New Carrier D308EX 19060D308CF D336EX 19060D336CF D355EX 19060D355CF D370EX 19060D370CF D390EX 19060D390CF D411EX 19060D411CF D433EX 19060D433CF D463EX 19060D463CF D488EX 19060D488CF D529EX 19060D529CF D557EX 19060D557CF D617EX 19060D617CF RD344650EX RD344650CF RD344717EX RD344717CF Note The service carriers listed above have a thin flange design. New Carrier DR308EX 19060DR308CF DR325EX 19060DR325CF DR336EX 19060DR336CF DR355EX 19060DR355CF DR370EX 19060DR370CF DR390EX 19060DR390CF DR411EX 19060DR411CF DR433EX 19060DR433CF DR463EX 19060DR463CF DR488EX 19060DR488CF DR529EX 19060DR529CF DR557EX 19060DR557CF DR617EX 19060DR617CF DR650EX 19060DR650CF DR717EX 19060DR717CF Note The service carriers listed above have a thin flange design. Use axle housing hardware kit 32 New Service Carriers Single Drive Axles Single Axle Single Reduction Carriers 19060S NS No Spin Carriers Spline 39 Involute Gearing Hypoid No Spin Diff Part Number Fastener Kit These new carrier units will directly replace single axle models 17060S NS with no modifications. New Carrier SN325EX 19060SN325CF SN355EX 19060SN355CF SN390EX 19060SN390CF SN411EX 19060SN411CF SN433EX 19060SN433CF SN463EX 19060SN463CF SN488EX 19060SN488CF SN529EX 19060SN529CF SN557EX 19060SN557CF SN650EX 19060SN650CF SN717EX 19060SN717CF Note The service carriers listed above have a thin flange design. New Carrier SNRBC617EX19060SNRBC617CF Spline 39 Involute Gearing Hypoid No Spin Diff Part Number Fastener Kit These new carrier units will directly replace single axle models 17060S NS PB with no modifications.

New Carrier SNR370EX 19060SNR370CF SNR390EX 19060SNR390CF SNR411EX
19060SNR411CF SNR463EX 19060SNR463CF SNR488EX 19060SNR488CF SNR529EX
19060SNR529CF SNR557EX 19060SNR557CF SNR617EX 19060SNR617CF SNR717EX
19060SNR717CF Note The service carriers listed above have a thin flange design. New Carrier 2.64
RS404264EX RS404264CF RS404285EX RS404285CF RS404293EX RS404293CF RS404308EX
RS404308CF RS404325EX RS404325CF RS404336EX RS404336CF RS404342EX RS404342CF
RS404355EX RS404355CF RS404370EX RS404370CF RS404390EX RS404390CF RS404411EX
RS404411CF RS404433EX RS404433CF RS404463EX RS404463CF RS404488EX RS404488CF
RS404529EX RS404529CF RS404557EX RS404557CF RS404617EX RS404617CF RS404650EX
RS404650CF RS404717EX RS404717CF Note 1 In certain Navistar applications, original Dana
Production Carriers are identified as 21060S, 21060L, 21060T and 21060D. Refer to the model
section of this IPL for those replacement part numbers. Note 1 In certain Navistar applications,
original Dana Production Carriers are identified as 21060S, 21060L, 21060T and 21060D. Model on
ID tag may be RD404. Note 1 In certain International applications, original Dana Production
Carriers are identified as 21060S, 21060L, 21060T and 21060D. Refer to the section of this IPL for
those replacement part numbers. Be sure to check spline configuration before ordering a
replacement carrier. Note 2 Diff Lock shift covers on these units are supplied with standard English
threaded air line ports. 32 35 New Service Carriers Single Drive Axles Single Axle Single Reduction
Carriers 21060S NS No Spin Carrier Gearing Hypoid No Spin Diff Part Number Fastener Kit These
new carrier units will directly replace single axle models 21060S NS and 22060S NS with no
modifications. New Carrier SN390EX 21060SN390CF SN411EX 21060SN411CF SN433EX
21060SN433CF SN463EX 21060SN463CF SN488EX 21060SN488CF SN529EX 21060SN529CF
SN557EX 21060SN557CF SN617EX 21060SN617CF Note The service carriers listed above have a
thin flange design.

Note 1 Dana carriers shown with GenTech gearing are for motor coach and bus applications. When
doing repairs or replacement of these axles, be sure to consult the OEM or verify the actual part
numbers from the serial tags before ordering carriers. New Carrier 3.08 RSP40308EX RSP40308CF
RSH40325EX RSH40325CF RSH40336EX RSH40336CF RSH40355EX RSH40355CF RSH40370EX
RSH40370CF RSH40390EX RSH40390CF RSH40411EX RSH40411CF RSH40433EX RSH40433CF
RSP40463EX RSP40463CF RSP40488EX RSP40488CF RSP40529EX RSP40529CF RSP40557EX
RSP40557CF RSP40617EX RSP40617CF RSP40650EX RSP40650CF RSP40717EX RSP40717CF
Note 1 Dana carriers are application specific. Some motor coach and bus applications require
Gentech gearing. New Carrier 4.88 RSH44N488EX RSH44N488CF RSH44N529EX RSH44N529CF
RSH44N557EX RSH44N557CF RSH44N617EX RSH44N617CF RSH44N650EX RSH44N650CF
RSH44N717EX RSH44N717CF Note 1 Dana carriers are application specific. These 23060SH BC
Bus Coach carriers are unique and used in specific applications. In coach applications the 23060SH
BC have Spicer GenTech gearing. New Carrier SHBC463EX 23060SHBC463CF SHBC488EX
23060SHBC488CF SHBC650EX 23060SHBC650CF Note 1 Dana carriers are application specific.
When doing repairs or replacement of these axles, be sure to consult the OEM or verify the actual
part numbers from the serial tags before ordering replacement carriers. 34 37 New Service Carriers
Single Drive Axles Single Axle Single Reduction Carriers P20060S Premium 40 Carrier Gearing
Hypoid Side Gear Part Number These new carrier units will directly replace single axle model
P20060S, P21060S, P22060S and P20060R models with brake retarder option with no modifications.
Tag on unit may be P20060D or RDP40. These units can be used as replacements for models 23070S
when a new yoke and slinger is used. These units can be used as replacements for models 23070S
NS when a new yoke and slinger is used.

See yoke section for proper selection SN370CF SN390CF SN433CF HX SN488CF SN529CF
SN617CF D Diff Lock Carrier Spline 36 Involute Gearing Hypoid Side Gear Part Number Fastener
Kit See Note 1. These new carrier units will directly replace models 21080D, 21090D, 23080D,

23085D, 23090D and 26090D with no modifications. See yoke section for proper selection D285CF D325CF D355CF D370CF D390CF D411CF D433CF D463CF D488CF D529CF D557CF D583CF D617CF D650CF Note 1 Carriers use diff lock cover, which is for standard applications. Some Navistar, Peterbilt and Kenworth vehicle applications call for carriers that use a special shift cover due to interference issues. Customers can use these carriers above and order special shift cover part number and cover plug part number separately S Carrier Bus Application VanHool 11.36 Spline 36 Involute Gearing Hypoid Side Gear Part Number These carriers are unique and application specific. Check OE or carrier part number and contact Dana Aftermarket Group for availability. Standard models replace standard and with no modifications. These new carrier units will directly replace models and with no modifications. Check carrier part number, for ratios not listed contact Dana Aftermarket Group. For early made models 19420, and use these units these and a new yoke and slinger. These new carrier units will directly replace controlled traction model 23430RH with no modifications. These new carrier units will directly replace controlled traction design models with no modifications. Model on ID tag may be R46170NS. New Carrier 3.

07 S170N307EX S170N307CF S170N321EX S170N321CF S170N342EX S170N342CF S170N358EX S170N358CF S170N373EX S170N373CF S170N391EX S170N391CF S170N410EX S170N410CF S170N430EX S170N430CF S170N456EX S170N456CF S170N478EX S170N478CF S170N525EX S170N525CF S170N538EX S170N538CF S170N557EX S170N557CF S170N614EX S170N614CF S170N683EX S170N683CF S170N717EX S170N717CF 43 New Service Carriers Single Drive Axles Single Axle Single Reduction Carriers S170R Retarder Ready Carrier Spline 46 Involute Gearing Ring Gear Diameter Side Gear Part Number 300GD101 These new carrier units directly replace single axle models S23170R, S26170R and S30170R with no modifications. New Carrier 4.30 S170BC430EX S170BC430CF S170BC478EX S170BC478CF S170D Diff Lock Carrier Spline 46 Involute Gearing Ring Gear Diameter Side Gear Part Number 300GD101 These new carrier units directly replace single axle models S21170D, S23170D, S25170D and tandem rearrear models R40170D, R46170D, R50170D with no modifications. New Carrier 4.30 S170DBC430EX S170DBC430CF S170DBC478EX S170DBC478CF S190 Standard Carriers Spline 46 Involute Gearing Ring Gear Diameter Side Gear Part Number 300GD101 Fastener Kit These new carrier units will directly replace single axle models S23190, S26190, S and tandem rear rear models R46190, R52190, R with no modifications. New Carrier 2.

<https://ayurvedia.ch/edx-sem-manual>